

# Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07915 | Date: 9/23/2021

## Inspection Photos



**Photo 1.** Facing southwest along the main road in the canyon. The road has been graded however, there is still culvert maintenance needed. Red arrow points to erosion undercutting by the culvert which will end up eroding.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 9/23/2021



## Inspection Photos



**Photo 2.** This culvert outlet has been repaired with rock armoring. One issue is observed, there is no diversion for stormwater off the road shown at red arrow which will cause stormwater to pool in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 9/23/2021



## Inspection Photos



**Photo 3.** Facing west toward the access road ascending the hillside. The road has been graded. The culvert inlet shown in photo 4 is near the red arrow.



**Photo 4.** The culvert outlet is eroded and does not have outlet protection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 9/23/2021



## Inspection Photos



**Photo 5.** Facing west along the road ascending the hillside.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 9/23/2021



## Inspection Photos



**Photo 6.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 9/23/2021



## Inspection Photos



**Photo 7.** Facing toward the cut slope of the location. The noxious weeds along the cut slope were not controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 9/23/2021