

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2021

Submitted Date:

09/22/2021

Document Number:

699503192

FIELD INSPECTION FORM

Loc ID: 320384 Inspector Name: MEDINA, JUSTIN On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10711
Name of Operator: PAINTED PEGASUS PETROLEUM LLC
Address: 16820 BARKER SPRINGS RD #521
City: HOUSTON State: TX Zip: 77084

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		jm@p3petro.com	
		dnr_cogccenforcement@state.co.us	
		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203605	WELL	SI	01/01/2019	GW	001-09165	JACKIE 1	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: [Weeds unmanaged on location, wellhead, lease road. Unable to visually inspect due to weed growth.](#)

Corrective Action: [Comply with COGCC housekeeping rules](#)

Date: 01/24/2021

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: [plunger lift automation](#)

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: [Plumbed to surface according to previous inspection](#)

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment: [Hard to find markers due to weed growth](#)

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS			,
Comment: Unable to inspect due to weed growth.					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition:

Other (Content):

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Unable to inspect berms due to weed growth.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 203605 Type: WELL API Number: 001-09165 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well has been shut in since 10/1/18, delinquent for Mechanical Interty Test. Contact COGCC engineering

Corrective Action: Well must be either:
1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or
2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Date: 01/15/2021

BradenHead

Date of Last Brhd Test: 05/01/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual Bradenhead test is not current. Contact COGCC engineering

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 9/22/21 at approximately 1500 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Jackie 1 Company Name- Painted Pegasus Petroleum API- 05-001-09165 In Adams County Colorado. While there, I observed Shut in well. This is a follow up inspection from document # 699502141 Corrective Actions are Delinquent. During this inspection the following possible compliance issues were observed: Weeds unmanaged on location, unable to visually inspect other equipment due to weed growth. Comply with COGCC housekeeping rules 1/15/21 Well has been shut in since 10/1/2018, delinquent for Mechanical Integrity Test. Contact COGCC engineering. Comply with COGCC Mechanical Integrity Testing Rules 9/22/21 Annual bradenhead test is not current. Contact COGCC Engineering. Comply with COGCC annual bradenhead testing rules. 10/2/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	09/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503193	Inspection Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540522