

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863



Photo 1 WH sign



Photo 2 weeds growing around WH

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863



Photo 3 Stained soil around WH



Photo 4 ancillary equipment

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863



Photo 5 Pump Jack



Photo 6 Horiz. Heated Sep., ECD

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863



Photo 7 dead weeds inside Separator/ECD fencing

Photo 8 dead weeds inside Separator/ECD fencing

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863



Photo 9 Flow line manifold




Photo 10 Stained soil by the flow line manifold

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863



Photo 11 TB sign



Photo 12 TB

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863



Photo 13 Dead weeds in TB berm



Photo 14 Dead weeds around PW vessel

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863



Photo 15 Dead weeds in TB berm



Photo 16 Dead weeds in TB berm, Gas Meter Run

Inspection Photos

Location Name: Marie Gerhardt B 2

Location ID: 317863




Photo 17 Card in meter box indicates that calibration is not current

Photo 18 Stained soil by Crude tank

Inspection Photos
Location Name: Marie Gerhardt B 2
Location ID: 317863




Photo 17 Stained soil by Crude tank flow line