

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2021

Submitted Date:

09/28/2021

Document Number:

690008483

FIELD INSPECTION FORMLoc ID 307124 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10379

Name of Operator: HARBURG* RUDOLPH W

Address: 1020 MAPLETON AVE

City: BOULDER State: CO Zip: 80304

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Harburg, Rudy	(303) 931-8099	rudy.harburg@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216916	WELL	PR	01/01/2013	GW	069-06103	WESTWARD 2	TA

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type WELLHEAD

Comment: Sign not posted or information inaccurate at oil and gas location.

Corrective Action: Install sign to comply with Rule 605.a

Date: 09/06/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: Unused Propane Tank At Battery.

Corrective Action:

Date:

Type WEEDS

Comment: Weeds at wellhead and battery

Corrective Action: n: Comply with Rule 606

Date: 08/13/2021

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.372920,-105.065880	
Comment:						
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Secondary containment is not sufficiently impervious to contain spilled or released materials.			
Corrective Action:	Install liner material to ensure spill or released materials will be maintained with containment structure.			Date: 09/06/2021

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil tank.			
Corrective Action:				
Date:				

Wells Served By Facilities Above

API Number
069-06103

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	YES		
Comment:	Well is not closed to atmosphere		
Corrective Action:	Close well to atmosphere as directed by Rule 434.b.(1)		Date: 09/29/2021

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 216916 Type: WELL API Number: 069-06103 Status: PR Insp. Status: TA

COGCC Comments

Comment	User	Date
<p>Follow up inspection.</p> <p>On Tuesday, September 28, 2021 at 10:59, I, Craig Carlile conducted an on-site follow up inspection at: WESTWARD-65N69W25SWSE, location number: 307124 Operated by: HARBURG* RUDOLPH W 10379 While there I observed: Audible lead at wellhead, requested FLIR inspection resources to be dispatched to location to accurately document gas leakage from wellhead master valve. Previously cited weed, signage and unused equipment corrective actions have not been accomplished. Weather: Skies: Partly Cloudy, Wind: Calm, Temp 72 Degrees F Photos from previous inspection on August 5, 2021 and from September 28, 2021 demonstrate the corrective actions have not been accomplished. Comments from previous inspection are repeated below: "On Thursday, August 5, 2021 at 10:23, I, Craig Carlile conducted an on-site inspection at location number: 307124, location name: WESTWARD- 65N69W25SWSE Operated by: HARBURG* RUDOLPH W 10379 While there I observed: Audible leak at wellhead, lack of signage at wellhead and battery, uncontrolled weeds at wellhead and battery, unused equipment at battery (propane tank) Note: Last production report available in COGCC data base 12/1/2015, documents in review include NOAV actions addressing this issue. Additionally, a Form 6(N) has been submitted and approved with a status date of 7/19/2021, no evidence of plugging activity evident at time of inspection. Weather: Skies: Clear, Wind: Calm, Temp 76 Degrees F" This is a summary of the inspection report.</p>	carlilec	09/28/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690008484	Current Inspection.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542026
690008486	August 5, 2021 Inspection.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5542027