

Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel



Photo #1 looking mostly north from well pad at area of former flare pit.
The fence on the right hand side of pit was removed to allow
equipment access to the pit.

Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel



Photo #2 staining observed at entry to pit.

Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel



Photo #3 looking west from entry to pit. It was observed that soil had been removed from pit and stored on pad surface in a liner.



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #4 the fence on left of photo is east, the downgrade side of facility (east).



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #5 Stained soil observed, soil had strong hydrocarbon odor.



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #6 looking mostly south from pad.

Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel



Photo #7 fence around well had been partly removed. Well was SI at the time of inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #8 treater north-west of wellhead.

Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel



Photo #9 bag seen in photo was sampled with a PID. PID indicated 138 total VOC. Pit bottom PID read 48 ppm total VOC. Sample had odor and had visual indication of hydrocarbon impact, impact was seen at pit bottom and around the circumference of entire pit.



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #10 photo ~70 feet from east side of pit, Sage Creek (dry) next to county road 37.



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #11 seasonal creek (Sage Creek) ~70 from pit.



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #12 photo taken from state landboard public access surface adjacent to location. Pit can be seen just above the fence post in center of photo.



Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel

Photo #13 looking mostly south at former pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel

Photo #14 close up of pit looking south west.



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #15 inside old fenced area of pit.



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #16 stockpiled soil that was reported as removed from pit.
Corrective Action: remove stock piled soil. During inspection, the waste was sampled by Bayless Contractor for disposal-characterization.

Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel



Photo #17 tank is ~35 feet west of wellhead. Tank labeling indicates that tank is being used to vent gas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

No Pit id #,

REM Project # 19966

Location #316764

Inspection Date: 9/15/2021

All Photos taken by Kris Neidel

Photo #18 sign near wellhead.

Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel



Photo #19 fencing at tank battery.



Inspection Photos
No Pit id #,
REM Project # 19966
Location #316764
Inspection Date: 9/15/2021
All Photos taken by Kris Neidel

Photo #20 looking south at tank battery.