

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2021

Submitted Date:

09/22/2021

Document Number:

700703265

FIELD INSPECTION FORMLoc ID 336043 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297112	WELL	PR	03/01/2021	GW	103-11322	FREEDOM UNIT 197-28A1	PR
297114	WELL	PR	06/01/2013	GW	103-11321	FREEDOM UNIT 197-28A2	PR
297118	WELL	PR	06/01/2013	GW	103-11320	FREEDOM UNIT 197-28A3	PR
297119	WELL	PR	09/01/2013	GW	103-11319	FREEDOM UNIT 197-28A4	PR
415323	WELL	PR	01/19/2011	GW	103-11631	FREEDOM UNIT 197-28A8	PR
415332	WELL	PR	06/01/2013	GW	103-11632	FREEDOM UNIT 197-28A7	PR
415359	WELL	PR	02/01/2014	GW	103-11633	Freedom Unit 197-28A5	PR
415364	WELL	PR	05/05/2020	GW	103-11634	FREEDOM UNIT 197-28A6	PR
415380	WELL	PR	03/01/2018	GW	103-11636	FREEDOM UNIT 197-28A9	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 9/21/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Freedom Unit 197-28A, at Location # 336043 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Signs of erosion near manifold

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 2		corrective date
Comment:	chemical tanks in plastic and metal containments		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Pump skids		
Corrective Action:		Date:	

Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	297112	Type:	WELL	API Number:	103-11322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	297114	Type:	WELL	API Number:	103-11321	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	297118	Type:	WELL	API Number:	103-11320	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	297119	Type:	WELL	API Number:	103-11319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	415323	Type:	WELL	API Number:	103-11631	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	415332	Type:	WELL	API Number:	103-11632	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	415359	Type:	WELL	API Number:	103-11633	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	415364	Type:	WELL	API Number:	103-11634	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
		Ditches				

Comment: 1. Signs of erosion near manifold

Corrective Action: Install or repair required BMPs

Date: 10/29/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402819984	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5537917
700703275	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5537901