

Inspection Photos

API: 071-09140

Operator: OGRIS OPERATING LLC

Inspection Date: 9/28/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 9/28/2021

Inspection Photos



Photo 1. Facing northeast along the main access road. There is erosion along the side of the road which needs BMP's to prevent further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 9/28/2021

Inspection Photos



Photo 2. Facing west along access road. The culvert is filled in with sediment and stormwater from the road is not being directed toward the culvert from the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 9/28/2021

Inspection Photos



Photo 3. There is noxious weeds along the access road traveling to the location. Arrow points to Canada thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09140 | Date: 9/28/2021

Inspection Photos



Photo 4. Facing toward the location.

