

Caerus Piceance LLC
O2E
Location # 334695



location



location



Caerus Piceance LLC
O2E
Location # 334695



location



location



Caerus Piceance LLC
O2E
Location # 334695



Lack of stabilization/erosion




Lack of stabilization/erosion



Caerus Piceance LLC
O2E
Location # 334695



Open ended piping



Staining



Caerus Piceance LLC
O2E
Location # 334695



Staining



Improperly marked dead man



Caerus Piceance LLC
O2E
Location # 334695



Improperly marked dead man



South East corner of tank battery