

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 1 WH sign**



**Photo 2 WH**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 3 pump jack**



**Photo 4 ancillary equip.**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 5 TB sign**



**Photo 6 TB**



**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 7 Stained soil by crude oil tank load out line.**



**Photo 8 Flow line manifold**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 9 Gas Meter Run**



**Photo 10 Card in meter box indicates calibration is not current.**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 11 Stained soil by the Gas Meter Run**



**Photo 12 Horizontal Heated Separator.**