

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate, its beginning to fade and will need to be addressed in the near future		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	ancillary equip. has steel pipe and round stock		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1	corrective date	
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241054 Type: WELL API Number: 123-08842 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/12/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 9/29/2021 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: James S. Haley Trustee #3 at API #05-123-08842 in Weld County Colorado. While there, I observed a well site, PR at the time of inspection. Follow up to Doc # 699303829. During this inspection the following possible compliance issue has been addressed: 603.f housekeeping: weeds growing along acces road and around well site ROW have been cut. See attached photos. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	09/29/2021

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304352	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543865