

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/01/2021

Submitted Date:

09/20/2021

Document Number:

700900721

**FIELD INSPECTION FORM**Loc ID 320387 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                   | Comment |
|--------------|-------|-------------------------|---------|
|              |       | jmustacchia@p3petro.com |         |
|              |       | khubbard@P3Petro.com    |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 203625      | WELL | PR     | 09/01/2019  | OW         | 001-09185 | KELTON A-3    | SI          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WEEDS  |       |            |
| Comment:           | Weeds through out location   |       |            |
| Corrective Action: | Location is within a designated setback location, remove trash, debris and weeds per Rule 604.c.(2)P. Corrective Action Date 10/8/2021. See attached photo # 1 through 3 | Date: | 10/08/2021 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                                 |                                  |       |                 |
|---------------------------------|----------------------------------|-------|-----------------|
| Type: Vertical Heated Separator | # 1                              |       | corrective date |
| Comment:                        |                                  |       |                 |
| Corrective Action:              |                                  | Date: |                 |
| Type: Pump Jack                 | # 1                              |       |                 |
| Comment:                        |                                  |       |                 |
| Corrective Action:              |                                  | Date: |                 |
| Type: Deadman # & Marked        | # 4                              |       |                 |
| Comment:                        |                                  |       |                 |
| Corrective Action:              |                                  | Date: |                 |
| Type: Bird Protectors           | # 1                              |       |                 |
| Comment:                        |                                  |       |                 |
| Corrective Action:              |                                  | Date: |                 |
| Type: Bradenhead                | # 1                              |       |                 |
| Comment:                        | Appears to be plumbed to surface |       |                 |
| Corrective Action:              |                                  | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | <50 BBLS | PBV FIBERGLASS |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                | Date:   |        |

**Paint**

|                 |          |
|-----------------|----------|
| Condition       | Adequate |
| Other (Content) |          |

|                  |  |  |  |  |  |  |
|------------------|--|--|--|--|--|--|
| Other (Capacity) |  |  |  |  |  |  |
| Other (Type)     |  |  |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

|                    |   |          |           |         |                       |       |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |       |
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | 39.905780,-104.579872 |       |
| Comment:           |   |          |           |         |                       |       |
| Corrective Action: |   |          |           |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Wells Served By Facilities Above**

|            |
|------------|
| API Number |
| 001-09162  |
| 001-09185  |

**AirsID**

|            |        |
|------------|--------|
| API Number | AirsID |
|------------|--------|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 203625 Type: WELL API Number: 001-09185 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Appears to be plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Wednesday September 1, 2021 at approximately 11:20am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Kelton A3, Painted Pegasus Petroleum LLC, at API # 001-09185 in Adams County Colorado.</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed: Weeds, trash, debris &amp; unnecessary equipment. Location is within a designated setback location, remove trash, debris and weeds per Rule 604.c.(2)P. Corrective Action Date 10/8/2021. See attached photo # 1 through 3</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | finkenbc | 09/20/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402817329    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5535927">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5535927</a> |
| 700900722    | Inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5535918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5535918</a> |