

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #1 East side of Tanks.



Photo #2 North side of Tanks.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #3 South East side of Vertical Separators.



Photo #4 South East side of Pump Jack.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #5 South West side of tank.



Photo #6 North side of new pad for potential ECD.



Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #7 North side of ECD, East of concert pad.



Photo #8 South side of ECD.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #9 south side of versus unused equipment.



Photo #10 North side of versus unused equipment.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo # 11 South West side of crude tank, stained soil from leaking tank.



Photo #12 South side of crude tank, stained soil from leaking tank.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #13 South West side of East crude tank, stained soil from leaking tank.



Photo #14 East side of East crude tank, stained soil from leaking tank.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #15 stained soil under valves in-between crude tanks



Photo #16 West side of unmaintained berm around tanks.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #17 West side of unmaintained berm around tanks.



Photo #18 East side of unmaintained berm around tanks.



Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #19 West side of unmaintained berm around tanks



Photo #20 unused fiberglass pipe along pit.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #21 unmaintained pit .



Photo #22 unmaintained pit.

Inspection Photos
Location Name: Simpson A9
Location ID: 319940



Photo #23 Hydrocarbons in pit below discharge tub.



Photo #24 unmaintained pit.