

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2021

Submitted Date:

10/01/2021

Document Number:

700300277

**FIELD INSPECTION FORM**Loc ID 306783 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
| , General    |       | sjninspections@ikavenergy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 264756      | WELL | PR     | 09/17/2002  | GW         | 067-08752 | JAMES COLE B 2 | PR          |

**General Comment:**[Follow up inspection to 9/10/21 inspection doc#700300270](#)

**Location**Overall Good: ☐**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

**Good Housekeeping:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | OTHER   |       |  |
| Comment:           | CA satisfactorily performed, impacted material removed from east side of compressor |       |  |
| Corrective Action: |   | Date: |  |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 264756 Type: WELL API Number: 067-08752 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Complaint**

Comment:

CA regarding bare section of sound panel interior has been completed with R 13 insulation and poultry mesh. No additional sound measurements taken at this time, previous measurements were within thresholds in Rule 423. Continuing best management, engineering and maintenance practices are encouraged with a focus on low frequency noise transmission, which seems to be the nature of the complaints south of the location.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                            | URL   |
|--------------|--|---|
| 700300281    | repaired section of sound panel        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545916">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545916</a> |
| 700300282    | lube oil and impacted material removed | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5545917</a> |