

Inspection Photos
Location Name: Standley 5-2
Location ID: 335697



Pic 1 ECD not connected to well.



Pic 2 basebeam in front of well. Rods have been installed on first well, no rig on location.

Inspection Photos
Location Name: Standley 5-2
Location ID: 335697



Pic 3 tanks.



Pic 4 separator, ECD. Automation equipment.