

Inspection Photos
Operator: Arkoma
Facility: 067-09531
Date: 9/20/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with smooth brome, western wheatgrass, and sunflowers.



Photo 3. View of seeding musk thistles within the southern project area, need to be removed. Approximately 30 individuals observed.



Photo 4. View of area in the eastern fill slope where stormwater erosion (approx. 3 ft wide and 2ft deep channel) is occurring due to oversaturation in the slope. Stabilization is needed here.




Photo 5. View of cobble BMP in southeastern well pad diversion. BMP needs repair and additional, more robust reinforcement to stabilize erosion here.



Photo 6. View of reference area comprised of sagebrush shrubland with snakeweed, James galleta, buckwheat, and penstemons in the understory.