

Inspection Photos
Operator: Logos
Facility: 067-05469
Date: 9/20/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner of the working area, facing southward. Seeding is conducted. Straw mulch and some seedlings observed. Mature vegetation remains weedy.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland with James galleta, rubber rabbitbrush, snakeweed, Indian paintbrush, and squirreltail.