



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds all around equipment/location		
Corrective Action:	Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements	Date:	10/13/2021

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Barbless wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fabricated steel pipe and hog fence.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	

**Equipment:**

Type:		#		corrective date
Ancillary equipment		# 1		
Comment:	Electric panel, meter box and transformers			
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:	appears to be plumbed to surface			

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241201 Type: WELL API Number: 123-08989 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/09/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Wednesday 9/29/2021 at approximately 1240 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p align="center">Pete Montoya B #2 at API #05-123-08989 in Weld County Colorado.</p> <p>While there, I observed a wellsite, PR at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      606 housekeeping: Weeds growing around location/equipment, CA date 10-13-2021.                      See attached photos.                      Location: dry, Weather: clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	09/29/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402827091	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543871">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543871</a>
699304350	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543864">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543864</a>