



Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Weeds overgrown along access rd.		
Corrective Action:	Comply with Rule 606		Date: 10/13/2021
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			Date:
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds overgrown all around well site		
Corrective Action:	Comply with Rule 606		Date: 10/13/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date
Comment:	electric motor		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel, meter box and transformers		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See related inspection Doc #699302433 for information concerning shared facilities and equipment.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 241242 Type: WELL API Number: 123-09030 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/03/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: appears to be plumbed to surface

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 9/29/2021 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Teets-Perrin 4 at API #05-123-09030 in Weld County Colorado. While there, I observed well site, PR at the time of inspection. During this inspection the following possible compliance issues were observed: Rule 606 housekeeping: weeds overgrown along access and throughout wellsite. CA date 10-13-2021. See attached photos. Location is wet, weather is overcast. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	09/29/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402827093	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543873">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543873</a>
699304357	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543867">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5543867</a>