

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2021

Submitted Date:

10/06/2021

Document Number:

690008530

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 329475 _____ Carlile, Craig _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 47120 _____
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP _____
 Address: P O BOX 173779 _____
 City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80217- _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 _____ Number of Comments
 0 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Oxy		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249605	WELL	SI	04/01/2020	GW	123-17408	MAYER 22-11L	PA

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Plunger Lift	# 0				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 249605 Type: WELL API Number: 123-17408 Status: SI Insp. Status: PA**COGCC Comments**

Comment	User	Date
Well has been plugged and is awaiting casing cut. Battery remains at 40.20896, -104.88032 serving remaining active wells.	carlilec	10/06/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690008531	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5548734