

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric box, anntenna has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Ancillary equipment		# 1		
Comment:	meter box, electric panel and transformers			
Corrective Action:			Date:	
Other		# 1		
Comment:	phone line and anntenna			
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:	appear to be plumbed to surface			
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:			Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241146 Type: WELL API Number: 123-08934 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, valves are closed electric panel is shut off and there is no meter on the meter box

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 11/01/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appears to be plumbed to surface.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10/6/2021 at approximately 1125 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up inspection to Doc # 699303761 and 699304253. Margaret Twombly B #3 at API #05-123-08934 in Weld County Colorado. While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues have been addressed: 605.g Signs: WH sign is faded and has fallen to the ground has been updated and attached to hof fence around pump jack. 606 Housekeeping: Weeds all around well site have been cut. There is a wooden pole with an antenna on it that has fallen over and is leaning on its fencing that needs to be addressed. See attached photos. Location: dry, Weather: clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	10/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304367	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5549082