

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Pump Jack	# 1				
Ancillary equipment	# 1	Electric panel, meter box and transformer			
Prime Mover	# 1	electric motor			
Bradenhead	# 1	appears to be plumbed to surface			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See related inspection Doc #699303784 for information concerning shared facilities and equipment.				
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
-----------	----------------------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 240229 Type: WELL API Number: 123-08017 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/06/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10/6/2021 at approximately 1510 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up to inspection Doc # 699303786 and 699304078. Neff 1 at API #05-123-08017 in Weld County Colorado. While there, I observed a wellsite, PR at the time of inspection. During this inspection the following possible compliance issues have been addressed: 606 Housekeeping: dead weeds around location have been cut. 1002.f.(2)B Housekeeping: Drum of oil on location has been removed. See attached photos. Location: dry, Weather: clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. This is a field inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.</p>	revasr	10/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304375	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5549086