

Inspection Photos

API: 055-06101

Operator: MANZANO LLC

Inspection Date: 10/5/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 10/5/2021

Inspection Photos



Photo 1. Drone aerial photo facing southwest along the access road. A pipe riser remains at the red arrow. The access road has not been reclaimed and the location is shown at the yellow arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 10/5/2021

Inspection Photos



Photo 2. Drone aerial photo facing northwest along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 10/5/2021

Inspection Photos



Photo 3. Aerial image of the location shows it has not been recontoured and reclaimed. The location disturbance is approximately 3.3 acres.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 10/5/2021

Inspection Photos



Photo 4. The pipeline risers still remain at the location shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 10/5/2021

Inspection Photos



Photo 5. Facing southwest overlooking the location. There are multiple areas of erosion along the cut slope and fill slope shown at red arrows.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 10/5/2021

Inspection Photos



Photo 6. The pit remains and is filled in with stormwater. This photo shows the erosion along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 10/5/2021

Inspection Photos



Photo 7. Facing southeast toward the location. The location disturbance is approximately 3.3 acres.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 10/5/2021