



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment:

PHOTO 3: VEGETATION OVERGROWTH ON LOCATION.  
PHOTO 4: TALL GRASS AND WEEDS GROWING DOWN THE CENTERLINE OF THE ENTIRE ROW (FIRE HAZARD FOR VEHICLES TRAVELING THE ROW).

Corrective Action:

MAINTAIN VEGETATION IN COMPLIANCE WITH RULE606.

Date: 10/14/2021

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PIT

Comment:

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Prime Mover

# 1

Comment:

INSIDE HOUSE

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Vertical Separator

# 1

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment:

TELEMETRY EQUIPMENT

Corrective Action:

Date:

Type: Deadman # & Marked

# 1

Comment:

ALL HAVE MARKERS

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	SOUND WALL ON NORTHWEST CORNER OF PIME MOVER HOUSE.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 217538 Type: WELL API Number: 071-06315 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat: 37.193663      Long: -104.709218

Reference Point: SE      Other: \_\_\_\_\_      Length: 100      Width: 40

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment: **NO PIT PERMIT ON FILE**

Corrective Action **Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 908.a.**

Date: 11/08/2021

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
695104917	INSP. PHOTOS	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5550019">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5550019</a>