

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: CATTLE PANEL AROUND WELLHEAD, PUMPJACK AND COMPRESSOR.

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Bradenhead # 1

Comment: IS PLUMBED TO SURFACE

Corrective Action:

Date: _____

Type: Compressor # 1

Comment:

Corrective Action:

Date: _____

Type: Gas Meter Run # 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date: _____

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: TELEMETRY EQUIPMENT

Corrective Action:

Date: _____

Type: Vertical Separator # 1

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No

Comment:

Corrective Action:

Date: _____

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 217510 Type: WELL API Number: 071-06287 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 113487 Lat: 37.202416 Long: -104.715715

Reference Point: SE Other: _____ Length: 60 Width: 30

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: NONE

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: NO

Comment: PHOTO 3: : Less than 2-feet of freeboard. CALL ZEKE SANCHEZ WITH EVERGREEN TO ADDRESS FLUID LEVEL.

Corrective Action Lower fluid level so at least two feet of freeboard exists per Rule 902.b. MAINTAIN A MINIMUM OF 2' FREEBOARD MEASURED FROM GROUND LEVEL (NOT THE TOP OF BURM) IN PRODUCED WATER PIT. NOTE: WATER PULLED ON LOCATION AS I WAS CONDUCTING MY INSPECTION AND STARTED PULLING THE PIT.

Date: 10/08/2021

COGCC Comments

Comment	User	Date
<u>THIS IS A FOLLOW UP TO INSP. DOC #690200966, CA'S HAVE BEEN ADDRESS HOWEVER IT DOES NOT APPEAR THAT THIS PIT IS BEING MAINTAINED WITH AT LEAST 2' OF FREEBOARD. THIS IS THE SECOND NOTICE OF THIS CORRECTIVE ACTION.</u>	beardslt	10/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104923	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5550022