

Inspection Photos

Loc ID: 386769

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/7/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 1. Facing north at the beginning of the access road. The road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 2. Facing northeast along the access road. The road has not been recontoured and reclaimed. There is an erosion channel developing along the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 3. Facing east along the access road. There is erosion along this area of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 4. Facing east along the access road and toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 5. Facing south toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 6. Facing southeast toward the fill slope of the location. There are mostly undesirable weeds (Russian thistle) growing along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 7. There are erosion channels along the fill slope which can be seen better in aerial imagery (photo 13). Arrow points to undesirable weeds, Russian thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 8. Facing northwest toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 9. There are signs of erosion occurring off the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 10. Drone aerial photo facing east toward the access road and location shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 11. Drone photo facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 12. Drone photo facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 13. Facing down toward the location shows erosion along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 14. Facing down toward the cut slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021

Inspection Photos



Photo 15. Drone photo facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc #386769 | Date: 10/7/2021