

Inspection Photos
Operator: Simcoe
Facility: 067-07464
Date: 10/6/2021



Photo 1. View of project area from the northeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing here with rubber rabbitbrush, Intermediate wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of area (approx. 50x 75) in the northern project area where little desirable vegetation is growing (observable vegetation is weedy Russian thistle). It appears that sediment deposition from the cutslope is settling here and choking desirable vegetation.



Photo 4. View of erosional channel (approx. 2-3 feet wide and 2 feet deep) within the northeastern corner of the project area.



Photo 5. View of erosional channeling and rilling within the eastern project area. Multiple erosional rills in the eastern project area.



Photo 6. View of reference area (in background) comprised of irrigated grass field with western wheatgrass and mixed pasture grasses.



Sediment
discharge
from the
northeastern
project area

10.06.2021

Photo 7. View of reference area (in background) comprised of irrigated grass field with western wheatgrass and mixed pasture grasses.



Photo 8. View of reference area comprised of sagebrush shrubland and pinyon-juniper woodland with James galleta, western wheatgrass, matt penstemon, and sticky rabbitbrush.