

Inspection Photos

Operator: Logos Operating
API: 067-05589
Date: 10/6/2021



Photo 1. View of project area from the northwestern corner facing center. Revegetation is progressing here with smooth brome and crested wheatgrass.



Photo 2. View of Russian thistle debris on the well pad, in former facilities area. Revegetation success needs to be assessed here.



Photo 3. View of more Russian thistle debris on the well pad along former access road area.



Photo 4. View of reference area comprised of sagebrush shrubland and pinyon-juniper woodland with James galleta, western wheatgrass, matte penstemon, and sticky rabbitbrush.