

Inspection Photos
Operator: Logos
API: 067-05565
Date: 10/6/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area facing eastward. Revegetation is progressing with western wheatgrass, intermediate wheatgrass, and smooth brome.



Photo 3. View of the southern fill slope from the southeastern corner facing westward.



Photo 4. View of cable debris in the southern project area.



Photo 5. View of reference area comprised of sagebrush shrubland and pinyon-juniper woodland with James galleta, western wheatgrass, matte penstemon, and sticky rabbitbrush.