

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Photo 3 Weeds growing all around location ROW

Photo 4 Weeds growing along access road

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Photo 5 Weeds growing all around location ROW



Photo 6 ECD, Horiz. Heated Sep.

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Photo 7 Gas Meter Run




Photo 8 Card in meter house indicates that calibration is not current

Inspection Photos
Location Name: MDM 33-14
Location ID: 331806



Photo 9 TB sign



Photo 10 TB