

Caerus Piceance LLC
K28NW
Location # 335428



Location/ lack of battery signage



location

Caerus Piceance LLC
K28NW
Location # 335428




Location/ lack of labeling on glycol vessels



Leaking A-valve or angle body



Caerus Piceance LLC
K28NW
Location # 335428




Staining under leaking A-valve



location

Caerus Piceance LLC
K28NW
Location # 335428



Glycol vessel dimensions



Glycol vessel dimensions



Caerus Piceance LLC
K28NW
Location # 335428



Glycol vessel dimensions



Glycol vessel dimensions



Caerus Piceance LLC
K28NW
Location # 335428



Glycol vessel dimensions



Glycol vessel dimensions