

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30SWNE

Location ID: 334657



Photo #5021 from entrance to location.



Photo #5022 from entrance to location.



Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30SWNE

Location ID: 334657



Photo #5023 from entrance to location.



Photo #5024 Glycol storage tank missing required information.



Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30SWNE

Location ID: 334657



Photo #5025 No battery sign located at the tank battery.



Photo #5026 Flowline heating insulation open ended and not capped.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources