

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2021

Submitted Date:

10/11/2021

Document Number:

697004652

FIELD INSPECTION FORM

Loc ID 307120 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10312
Name of Operator: PROSPECT ENERGY LLC
Address: 1036 COUNTRY CLUB ESTATES DR
City: CASTLE ROCK State: CO Zip: 80108

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gracey, Cameron		graceyservices@msn.com	
Giltner, Ward		wgiltner@yahoo.com	
Morgan, John		john.morgan@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216908	WELL	SI	05/01/2020	ERIW	069-06095	MSSU 30-7	SI

General Comment:

[Form 42 #402826259](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type OTHER		
Comment:	Wellhead enclosure		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Flow Line	# 1				
Comment:					
Corrective Action:		Date:			
Type: Bradenhead	# 1				
Comment:	Bradenhead valve is exposed at surface.				
Corrective Action:		Date:			
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216908 Type: WELL API Number: 069-06095 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>MDDY</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>05/01/2018</u>
			AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: Verification of Repairs Tbg psi: 0 psig Csg psi: 0 psig BH psi: 0 psig

Insp. Status: _____

Comment: MIT for verification of repairs, perforations are 4847'-4890', packer set @ 4789', ITP @ 0 psig, ICP @ 0 psig, IBH @ 10 psig, MIRU B&J Hot Oil pressure truck, pressure csg to 1280 psig and isolate wellbore from truck, 5 minute tbg @ 0 psig, csg @ 1280 psig, BH @ 15 psig, 10 minute tbg @ 0 psig, csg @ 1280 psig, BH @ 14 psig, 15 minute tbg @ 0 psig, csg @ 1280 psig, BH @ 12 psig, release pressure, SIW, RDMO.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697004653	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5551951