

# Construction and Stormwater Inspection

October 8, 2021

Operator: MORNING GUN EXPLORATION LLC #10656

Location ID: 465272

Inspection Document #: 697503330

Weld County, CO

SWSE Section 12 T7N R59W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Castor 7-59 /12  
Location ID: 465272



**Photo 1.** Drone aerial imagery illustrates the Castor location.

Inspection Photos  
Location Name: Castor 7-59 /12  
Location ID: 465272



**Photo 2.** Drone aerial imagery taken from location, facing North. Photo illustrates the topsoil stockpile and northeast sediment trap.



**Photo 3.** Drone aerial imagery taken from location, facing East. Photo illustrates construction of facilities, plugging operations at an adjacent Tindall well, and the southeast sediment trap.



**Photo 4.** Drone aerial imagery taken from location, facing South. Photo illustrates construction of facilities and the location entrance.



**Photo 5.** Drone aerial imagery taken from location, facing West. Photo illustrates the one well that has been spud.

Inspection Photos  
Location Name: Castor 7-59 /12  
Location ID: 465272



**Photo 6.** Photo taken from the entrance of location off CR 121.



**Photo 7.** Photo taken from the entrance of location off CR 121, facing North. Photo illustrates culvert needs maintenance, as it is currently blocked with gravel.

Inspection Photos  
Location Name: Castor 7-59 /12  
Location ID: 465272



**Photo 8.** Photo taken from the entrance of location off CR 121, facing West. Photo illustrates a vehicle tracking device BMP.



**Photo 9.** Photo taken from the southeastern location, facing North. Photo illustrates the perimeter ditch and berm BMP.

Inspection Photos  
Location Name: Castor 7-59 /12  
Location ID: 465272



**Photo 10.** Photo taken from the southwestern location, facing North. See comments under Photo 9.



**Photo 11.** Photo taken from the northeastern location, facing East. See comments under Photo 9.

Inspection Photos  
Location Name: Castor 7-59 /12  
Location ID: 465272



**Photo 12.** Photo taken from the western topsoil stockpile, facing East. Photo illustrates the stockpile has been temporarily stabilized.



**Photo 13.** Photo taken of the northwest sediment trap, facing East.

Inspection Photos  
Location Name: Castor 7-59 /12  
Location ID: 465272



**Photo 14.** Photo taken of the southwest sediment trap, facing East. Photo illustrates sediment accumulation from unconsolidated soil material from the well location due to wind erosion. The well location has not been properly stabilized.



**Photo 15.** Photo taken of the southeastern ditch BMP, facing East. Photo illustrates sediment accumulation from unconsolidated soil material from the well location due to wind erosion. The well location has not been properly stabilized.