

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 1: THE SOUND WALLS WERE REMOVED FROM THE LOCATION.

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 2: THE SOUND WALLS WERE REMOVED FROM THE LOCATION.

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 3: THE COMPRESSOR WAS MOVED TO INSPECT THE SOIL UNDER THE SKID. IT WAS DISCOVERED THAT THE SOIL UNDER THE SKID WAS NOT IMPACTED. THE COGCC AREA EPS WAS CONTACTED BY PHONE. THE INITIAL FORM 19 COULD NOT BE SUBMITTED VIA E-FORM ON 09/17/21 DUE TO IT ISSUES WITH THE WEBSITE. THE FORM WAS SUBMITTED 9/20/21.

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 4: THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR THAT OVERFLOWED CONTAINMENT WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN.

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 5: THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR THAT OVERFLOWED CONTAINMENT WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN. THE COMPRESSOR WAS PLACED BACK TO ITS ORIGINAL POSITION ON THE WELL PAD.

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 5: THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR THAT OVERFLOWED CONTAINMENT WAS REMOVED AND PROPERLY DISPOSED IN ACCORDANCE WITH THE OGRIS OPERATING WASTE MANAGEMENT PLAN. THE COMPRESSOR WAS PLACED BACK TO ITS ORIGINAL POSITION ON THE WELL PAD.

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 7: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 7: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT OUTLET.

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



PHOTO 9: THE ELECTRIC FENCE WAS REPAIRED.

APACHE CANYON 04-04 API# 05-071-09632 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104834



THE NFPA SIGN WAS REPLACED.



TANK CAPACITY LABEL