

## Inspection Photos

### Martin J Schaefer #2 Flowline – Spill #2



**Photo 1 – Spill location.**



**Photo 2 – Spill excavation. Free product observed on groundwater.**



## Inspection Photos

### Martin J Schaefer #2 Flowline – Spill #2




**Photo 3 – Spill excavation. Tape placed over cut end of flowline.**



**Photo 4 – Spill excavation. Tape placed over cut end of flowline. Leak observed from western end of cut flowline.**

## Inspection Photos

### Martin J Schaefer #2 Flowline – Spill #2



**Photo 5 – Leak observed from western end of cut flowline.**



**Photo 6 – Hole observed in removed portion of flowline.**



## Inspection Photos

### Martin J Schaefer #2 Flowline – Spill #2



**Photo 7 – Soil stored on location. No stormwater BMPs or lining present beneath soils pile. Excavated soils were dry.**



**Photo 8 – Soil stored on location. No stormwater BMPs or lining present beneath soils pile. Excavated soils were dry.**



## Inspection Photos

### Martin J Schaefer #2 Flowline – Spill #2



**Photo 9 – Soil stored on location. No stormwater BMPs or lining present beneath soils pile. Excavated soils were dry.**



**Photo 10 – Soil stored on location. No stormwater BMPs or lining present beneath soils pile. Excavated soils were dry.**



## Inspection Photos

### Martin J Schaefer #2 Flowline – Spill #2



**Photo 11 – Dry vegetation on soils pile.**



**Photo 12 – Dried scraped vegetation.**