



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Square tubing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		

Comment:	Rig pump and work tanks are grounded, fire extinguisher inspection tags are current.			Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Bradenhead valve is exposed at surface.			Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:	Separator is anchored.			Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:				Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV CONCRETE		,
Comment:	48 bbls				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	Crude oil tank is anchored.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type) _____	
--------------------	--

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No				
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 242897 Type: WELL API Number: 123-10688 Status: SI Insp. Status: WK

**Cement**

Cement Contractor

Contractor Name: Duco Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_ Cement Volume (sx): 200 sxs

Good Return During Job: \_\_\_\_\_ Cement Type: Class G Neat 15.8#

Comment: Csg has been jet cut @ 2500' KB, CICR set @ 2315' KB, perforations @ 2300' KB 6 SPF for annular squeeze #1, TIH with stinger and tbg, sting into CICR and condition wellbore, MIRU Duco cementers, establish circulation, mix and pump 90 sxs Class G Neat 15.8 ppg cement slurry (18.4 bbls total) through CICR, sting out of CICR and spot 10 sxs of slurry (2 bbls total) on top of CICR, RD cementers, lay down tbg to 2000' KB and reverse circulate clean, POOH with tbg and stinger, RU Ranger Energy Services e-line, RIH and perforate csg @ 1460' KB 6 SPF for annular squeeze #2, POOH with spent gun, RIH and perforate csg @ 1260' KB 6 SPF, POOH with spent gun, RIH with CICR and set @ 1275' KB, POOH with setting tool, RD e-line, TIH with tbg and stinger and condition wellbore, RU cementers, establish circulation, mix and pump 90 sxs Class G Neat 15.8 ppg cement slurry (18.4 bbls total) through CICR, sting out of CICR and spot 10 sxs of slurry (2 bbls total) on top of CICR.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/20/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697004657	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5553418">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5553418</a>