

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2021

Submitted Date:

10/06/2021

Document Number:

690008532

FIELD INSPECTION FORM

Loc ID 329220 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , Oxy | | COGCCInspections@Oxy.com | All Inspections |

General Comment:

| Location | | | | | |
|--|--|---------------------|---------------------|-------------|------------------|
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Signs/Marker: | | | | | |
| Type | WELLHEAD | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Emergency Contact Number: | | | | | |
| Comment: | | | | | Date: |
| Corrective Action: | | | | | Date: _____ |
| Good Housekeeping: | | | | | |
| Type | WEEDS | | | | |
| Comment: | Weeds at wellhead. | | | | |
| Corrective Action: | Comply with Rule 606 | | | | Date: 10/13/2021 |
| Overall Good: <input type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Fencing/: | | | | | |
| Type | WELLHEAD | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Equipment: | | | | | |
| Type: Plunger Lift | # 1 | | | | corrective date |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Tanks and Berms: | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | | | CENTRALIZED BATTERY | | , |
| Comment: | Shared battery services with location number: 329476 | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |

| | | | | | |
|--------------------|--|--|--|-------|--|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | | |
|--------------------|--|--|-------|--|
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Flaring:

| | | | | |
|--------------------|--|--|-------|--|
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| Routine wellhead inspection. Weeds at wellhead as can be seen in attached photo. | carlilec | 10/06/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402833396 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5548742 |
| 690008533 | Weeds | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5548735 |