

Inspection Photos

API: 071-08105

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/12/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 10/12/2021

Inspection Photos



Photo 1. Facing northeast toward the access road. The culvert shown at red arrow is filled in with sediment. Stormwater flowed across the road in this area. The culvert will need to be repaired and proper drainage to the culvert needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 10/12/2021

Inspection Photos



Photo 2. The pipeline has been covered with soil however this is not stabilized. Outlet protection at the culvert is needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 10/12/2021

Inspection Photos



Photo 3. Facing toward the culvert further along the road. Drainage toward the culvert was not corrected. The culvert is shown at the red arrow which to be repaired to allow proper drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 10/12/2021

Inspection Photos



Photo 4. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 10/12/2021