

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2021

Submitted Date:

10/11/2021

Document Number:

695104931

**FIELD INSPECTION FORM**

Loc ID 308147 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone        | Email                   | Comment                         |
|------------------|--------------|-------------------------|---------------------------------|
| Fitzgerald, Edie | 719-859-1394 | efitzgerald@ogrisop.com | <a href="#">All Inspections</a> |
| GEE, GREG        | 903-987-0353 | ggee@ogrisop.com        | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 262940      | WELL | PR     | 08/06/2006  | GW         | 071-07588 | HILL RANCH 10-09V | PR          |

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                      | #   | Comment   | Corrective Action  | Date  | corrective date |
|---------------------------|-----|---|--------------------|-------|-----------------|
| Type: Ancillary equipment | # 1 | Comment: <b>TELEMETRY EQUIPMENT</b>   | Corrective Action: | Date: |                 |
| Type: Deadman # & Marked  | # 5 | Comment:  | Corrective Action: | Date: |                 |
| Type: Bradenhead          | # 1 | Comment: <b>IS PLUMBED TO SURFACE</b>   | Corrective Action: | Date: |                 |
| Type: Progressive Cavity  | # 1 | Comment:  | Corrective Action: | Date: |                 |
| Type: Gas Meter Run       | # 1 | Comment: <b>CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.</b> | Corrective Action: | Date: |                 |
| Type: Prime Mover         | # 1 | Comment:  | Corrective Action: | Date: |                 |
| Type: Vertical Separator  | # 1 | Comment:  | Corrective Action: | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 262940 Type: WELL API Number: 071-07588 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 292551      Lat: 37.011040      Long: -104.867200

Reference Point: SE      Other: \_\_\_\_\_      Length: 120      Width: 40

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment: NONE

Corrective

Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description  | URL   |
|--------------|--------------|---|
| 695104932    | INSP. PHOTOS | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5554599">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5554599</a> |