

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment:

Corrective Action:

Date: 10/29/2021

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 1

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.828431,-104.566480

Comment:

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berm with crude					
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
001-09658

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

Flaring:

Type			
Comment:			
Corrective Action:			
			Date:

Inspected Facilities

Facility ID: 291955 Type: WELL API Number: 001-09658 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday September 23, 2021. at approximately 10:45am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Champlin Danford 44-32, Painted Pegasus Petroleum LLC, at API #001-09658 in Adams County Colorado. While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Weeds throughout location. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 10/29/20201. See attached photos #1 through 4 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	10/13/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900774	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5554670