

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2021

Submitted Date:

10/07/2021

Document Number:

697601609

FIELD INSPECTION FORMLoc ID 332949 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476185	OFF-LOCATION FLOWLINE	AC			-	Wellhead Line 21NWSW	EI

General Comment:

Inspection of area where flowline mapped by operator. Line runs from well to battery which is about 2300 feet southwest of well and across WCR 18.5.

Well inspected in separate inspection report (697601607)

Inspected FacilitiesFacility ID: 476185 Type: OFF- API Number: - Status: AC Insp. Status: EI**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Flowline as mapped by operator crosses public right of way or utility easement but is not marked per rule 1102.g.2. The attached aerial image shows the location of flowline 476185 as provided by Operator on form 44 submittal. The flowline runs from the Cary Walkling 1 (123-09717) well (north of WCR 18.5) to a battery (south of WCR 18.5) facility 480225 and must cross the public right of way at some point.

Inspection along both sides of WCR 18.5 did not find any signs indicating the location of flowline facility 476185 which is indicated to cross the county road right of way as shown on the attached Sept2020 aerial image. Attached aerial indicates mapped location of flowline and area which was searched for required sign(s) indicating crossing of right of way. The only signs observed along the section of road which was inspected were from a mid-stream gas gathering system with signs indicating operator of that line as Kerr McGee Gathering/Anadarko.

Corrective Action: Install markers that identify the location of flowline where it crosses the public right of way (WCR 18.5) following language per Rule 1102.g.(2)

Date: 11/07/2021**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402835141	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5549887
697601610	aerial image of inspection area (annotated)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5549883