

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2021

Submitted Date:

10/07/2021

Document Number:

701102029

FIELD INSPECTION FORM

Loc ID 316296 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 760 HORIZON DRIVE STE 400
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|-------------------------------------|
| Gas, UtahGasCorp | 970-693-6021 | inspections@utahgascorp.com | Inspection mail box |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 260674 | WELL | PR | 07/01/2019 | GW | 103-10166 | FOUNDATION CREEK 7430 | PR |

General Comment:

COGCC Routine Inspection Report Summary
Location is in a High Priority Habitat Area.
During this inspection the following compliance issues were observed:

- No battery sign at tank battery.
- Sediment movement on access road. Washing and riling of road surface and ditches.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:

| | | | |
|-------------------|--------------------------------------|--|-------|
| Type | Access | | |
| comment: | Access road damage from storm water. | | |
| Corrective Action | | | Date: |

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|--|------------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | No battery sign at tank battery. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | | Date: 01/08/2022 |

Emergency Contact Number:

| | | | |
|--------------------|-----|--|-------------|
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|--|------|--------|--|--|--|
| In Containment: No | | | | | |
| Comment: _____ | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |

Equipment:

| | # | | | corrective date |
|---------------------|-----|--|--|-----------------|
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Bradenhead | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|----------|---------|--------|
| CONDENSATE | 1 | <50 BBLS | Open Top | | , |
| Comment: _____ | | | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Paint

| | | | |
|------------------|----------|--|--|
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | 45 bbl | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | | |
|--------------------|----|--|--|-------|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 260674 Type: WELL API Number: 103-10166 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Ditches | | | | |
| Compaction | | | | | | |
| | | Compaction | | | | |

Comment: [Sediment movement on access road. Washing and riling of road surface and ditches.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 10/30/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 402835232 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5550004 |
| 701102042 | Inspection 701102029 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5549999 |