

Final Reclamation Inspection

October 13, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 332988

Inspection Document #: 697503352

Weld County, CO

SESW Section 6 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 1. Photo taken west of location, facing East. Photo illustrates all equipment has been removed and final reclamation activities have been completed

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 2. Photo taken from the western location, facing South. Photo illustrates the establishment of desirable plant species but bare areas were observed throughout the location. Some undesirable species, tumbleweeds, were observed and will need to be managed.



Photo 3. Photo taken from the north-central location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 4. Photo taken from the north-central location, facing North. See comments under Photo 2.



Photo 5. Photo taken from the eastern location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 6. Photo taken from the eastern location, facing South. Photo illustrates undesirable plant establishment with some desirable species throughout most of the access road.



Photo 7. Photo taken from the entrance of location off CR60, facing West. Photo illustrates undesirable plant establishment with little to no establishment of desirable species.

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 8. Photo taken from the entrance of location off CR60, facing North. See comments under Photo 7.



Photo 9. Photo taken from the southern access road, facing North. See comments under Photo 6.

Inspection Photos
Location Name: FRANK-65N67W 6SESW
Location ID: 332988



Photo 10. Reference photo taken west of the access road, facing North. Photo illustrates reference vegetative levels compared to reclamation areas.