

FORM  
INSPRev  
X/20

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2021

Submitted Date:

10/14/2021

Document Number:

693505591

## FIELD INSPECTION FORM

Loc ID 442629 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442627	WELL	PR	03/30/2017	OW	123-41940	Jacobucci 32S-323	PR
442628	WELL	PR	03/29/2017	OW	123-41941	Jacobucci 32S-203	PR
442630	WELL	PR	07/01/2021	OW	123-41942	Jacobucci 32S-303	PR
442631	WELL	PR	04/02/2017	OW	123-41943	Jacobucci 32S-403	PR
442632	WELL	PR	03/28/2017	OW	123-41944	Jacobucci 32S-343	PR
442805	WELL	PR	03/23/2017	OW	123-42023	Jacobucci 32S-423	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 13		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 7		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 6		

Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	150bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	13	300 BBLS	STEEL AST		40.007420,-104.913238
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**AirsID**

API Number	AirsID
------------	--------

**Wells Served By Facilities Above**

API Number
123-41943
123-41940
123-41942
123-41944
123-41941
123-42023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 442627 Type: WELL API Number: 123-41940 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/08/2020 Annual Brhd Completed? No  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: Submit reports  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 442628 Type: WELL API Number: 123-41941 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/08/2020 Annual Brhd Completed? No  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: Submit reports  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 442630 Type: WELL API Number: 123-41942 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/08/2020 Annual Brhd Completed? No  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: Submit reports  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 442631 Type: WELL API Number: 123-41943 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/08/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Submit reports

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 442632 Type: WELL API Number: 123-41944 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/08/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Submit reports

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 442805 Type: WELL API Number: 123-42023 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/08/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 10

Comment: Submit reports

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>Routine inspecton. At time of inspection it appears operator is performing reclamation. Trucks were actively hauling material off location.</u>	<u>silverr</u>	<u>10/14/2021</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>693505592</u>	<u>loc pic</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555564</u>