

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/14/2021

Submitted Date:

10/14/2021

Document Number:

695104963

**FIELD INSPECTION FORM**
 Loc ID 308658 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278031	WELL	PR	08/10/2005	GW	071-08407	CARMEL 21-33	PR
426650	TANK BATTERY	AC	04/14/2009		-	CARMEL-631S66W 33NENW	IO

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment: IS PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Progressive Cavity

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment:

Corrective Action:

Date:

Type: Deadman # &amp; Marked

# 4

Comment: ALL HAVE MARKERS

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: TELEMETRY EQUIPMENT

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		37.306170,-104.790989
Comment: PHOTO 3: TANK BATTERY DOES NOT APPEAR TO BE IN US (UNUSED EQUIPMENT).					

Corrective Action:	EITHER PUT TANK INTO USE OR REMOVE UNUSED EQUIPMENT PER RULE 606. IF TANK IS PUT BACK INTO USE TANK LABELING PER RULE 605.h. IS REQUIRED.	Date:	11/15/2021
--------------------	---	-------	------------

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	278031	Type:	WELL	API Number:	071-08407	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	426650	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	IO

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104964	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555807">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555807</a>