

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/14/2021

Submitted Date:

10/14/2021

Document Number:

695104975

**FIELD INSPECTION FORM**Loc ID 333396 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286291	WELL	PR	10/22/2006	GW	071-08936	LOOKING GLASS 34-4 TR	PR
286293	WELL	SI	11/01/2020	GW	071-08934	LOOKING GLASS 34-4	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PIT

Comment:

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Vertical Separator

# 2

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 2

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: **TELEMETRY EQUIPMENT**

Corrective Action:

Date:

Type: Deadman # &amp; Marked

# 8

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment: **BOTH ARE PLUMBED TO SURFACE**

Corrective Action:

Date:

Type: Progressive Cavity

# 2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment: **BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.**

Corrective Action:

Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 286291 Type: WELL API Number: 071-08936 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: Facility ID: 286293 Type: WELL API Number: 071-08934 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: WELL LAST PRODUCED OCT 2020Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: **PHOTO 3: OILY WASTE MIXED WITH WATER IN TR WELL PRIME MOVER ENGINE SKID.**

Corrective Action: **THIS IS THE SECOND NOTICE FOR THIS SAME CORRECTIVE ACTION FIX LEAKING EQUIPMENT. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO REMOVE OILY WASTE OR INSTALL WILDLIFE PROTECTION ON TR WELL PRIME MOVER SKID, 30 DAYS TO REPAIR EQUIPMENT.**

Date: 11/14/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 301195 Lat: 37.282740 Long: -104.785900

Reference Point: SE Other: \_\_\_\_\_ Length: 90 Width: 40

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: NONE

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Type: Produced Water Lined: NO Pit ID: 301197 Lat: 37.282890 Long: -104.785600

Reference Point: SE Other: \_\_\_\_\_ Length: 60 Width: 30

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment: NONE

Corrective Action

Date:

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	301197	1942019	
	301197	1942019	
	301195	1942018	

**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695104173, THIS IS A SECOND NOTICE OF THIS SAME CORRECTIVE ACTION. REPAIR LEAKING EQUIPMENT OR INSTALL PROTECTIVE BMP'S TO PROTECT WILDLIFE ON TR WELL PRIME MOVER SKID.	beardslt	10/14/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104976	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555813">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555813</a>