

TEP  
Broome 1  
Location # 335227



location



location

**TEP  
Broome 1  
Location # 335227**



**location**



**TEP  
Broome 1  
Location # 335227**



**Photo from first inspection document # 700702048  
of lack of stabilization/erosion**



TEP  
Broome 1  
Location # 335227



**Photo from first inspection document # 700702048  
of lack of stabilization/erosion**



**Photo from first inspection document # 700702048  
of lack of stabilization/erosion**

**TEP  
Broome 1  
Location # 335227**



**Photo from second inspection document # 700702702  
of lack of stabilization/erosion**



TEP  
Broome 1  
Location # 335227



**Photo from second inspection document # 700702702 of lack of stabilization/erosion**



**Photo from second inspection document # 700702702 of lack of stabilization/erosion**

**TEP  
Broome 1  
Location # 335227**



**Photo from third/this inspection document #  
700703365 of lack of stabilization/erosion**



TEP  
Broome 1  
Location # 335227



**Photo from third/this inspection document #  
700703365 of lack of stabilization/erosion**



**Photo from third/this inspection document #  
700703365 of lack of stabilization/erosion**

TEP  
Broome 1  
Location # 335227



**Photo from third/this inspection document # 700703365 of lack of stabilization/erosion**



**Photo from third/this inspection document # 700703365 of lack of stabilization/erosion**