

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2021

Submitted Date:

10/11/2021

Document Number:

699503249

FIELD INSPECTION FORMLoc ID 320037 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		JH@p3petro.com	
		jm@p3petro.com	
		khubbard@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202330	WELL	PR	03/01/2021	OW	001-07735	SANDIE 43-12	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds unmanaged on location, stained soil near pumping unit motor,		
Corrective Action:	Comply with COGCC housekeeping rules		Date: 07/16/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bird Protectors	# 1		
Comment:	Separator		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Bridal on pumping unit wire rope parted, and polish rod is bent.		
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Gas meter run automation		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Marked with steel rod		

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Unable to inspect berm due to weed growth on locaiton, weeds need to be removed.
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Weeds need to be removed to visually inspect berms
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 202330 Type: WELL API Number: 001-07735 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/05/2020

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: Annual Bradenhead test is not current. Contact COGCC engineering.

10/21/2021

Corrective Action: Comply with COGCC annual bradenhead testing rules.

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On 10/11/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:
 Well Name- Sandie 43-12
 Company Name- Painted Pegasus
 API- 05-001-07735
 In Adams County Colorado.
 While there, I observed PR well
 This is a follow up inspection from document #700900228 Corrective Actions are Delinquent

medinaj

10/11/2021

During this inspection the following possible compliance issues were observed:
 Weeds are unmanaged on location. Stained soil by pumping unit motor.
 Comply with COGCC housekeeping rules 7/27/20
 Annual Bradenhead test is not current. Contact COGCC engineering
 Comply with COGCC annual bradenhead testing rules. 10/21/21
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503250	Inspection Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556532