

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/12/2021

Submitted Date:

10/12/2021

Document Number:

699503255

**FIELD INSPECTION FORM**Loc ID 320477 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                            | Comment |
|--------------|-------|----------------------------------|---------|
|              |       | jm@p3petro.com                   |         |
|              |       | khubbard@p3petro.com             |         |
|              |       | jh@p3petro.com                   |         |
|              |       | dnr_cogccengineering@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 257347      | WELL | SI     | 09/01/2019  | OW         | 001-09416 | ABBOTT 12-21  | SI          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Weeds are unmanaged on location. Unable to visually inspect berms, and netting on open top tank due to weed growth. Stained soil, trash by tanks needs to be removed. Separator near wellhead needs to be removed.

Corrective Action: Comply with COGCC housekeeping rules 1/22/21

Date: 01/22/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bird Protectors

# 2

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Deadman # &amp; Marked

# 4

Comment:

Marked with metal pole

Corrective Action:

Date:

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment:

Automation

Corrective Action:

Date:

Type: Vertical Heated Separator

# 1

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Tanks and Berms:**

|                    |  |          |          |         |        |
|--------------------|--|----------|----------|---------|--------|
| Contents           | #  | Capacity | Type     | Tank ID | SE GPS |
|                    | 1  |          | Open Top |         | ,      |
| Comment:           | Unable to inspect netting due to weed growth on location |          |          |         |        |
| Corrective Action: |  |          |          |         | Date:  |

**Paint**

|                  |  |  |  |  |  |
|------------------|--|--|--|--|--|
| Condition        |  |  |  |  |  |
| Other (Content)  |  |  |  |  |  |
| Other (Capacity) |  |  |  |  |  |
| Other (Type)     |  |  |  |  |  |

**Berms**

|                    |   |                     |                     |             |
|--------------------|---|---------------------|---------------------|-------------|
| Type               | Capacity  | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |   |                     |                     |             |
| Comment:           | Unable to visually inspect due to weed growth on location |                     |                     |             |
| Corrective Action: |   |                     |                     | Date:       |

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| CRUDE OIL          | 2 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |  |  |  |
|------------------|----------|--|--|--|--|
| Condition        | Adequate |  |  |  |  |
| Other (Content)  |          |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |
| Other (Type)     |          |  |  |  |  |

**Berms**

|                    |   |                     |                     |             |
|--------------------|---|---------------------|---------------------|-------------|
| Type               | Capacity  | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              |   |                     |                     |             |
| Comment:           | Unable to visually inspect berms due to weed growth on location |                     |                     |             |
| Corrective Action: |   |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 257347 Type: WELL API Number: 001-09416 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 05/14/2020 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: Annual Bradenhead test is not current. Contact COGCC engineering 10/21/2021Corrective Action: A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. Date: \_\_\_\_\_**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On 10/11/21 at approximately 1430 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Abbott 12-21</p> <p>Company Name- Painted Pegasus</p> <p>API- 05-001-09416</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well</p> <p>This is a follow up inspection from document #700900419 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds are unmanaged on location. Unable to visually inspect berms, and netting on open top tank due to weed growth. Stained soil, trash by tanks needs to be removed. Separator near wellhead needs to be removed.</p> <p>Comply with COGCC housekeeping rules 1/22/21</p> <p>Annual Bradenhead test is not current. Contact COGCC engineering</p> <p>Comply with COGCC annual bradenhead testing rules. 10/21/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | medinaj | 10/12/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 699503256    | Inspection pictures | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556535">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5556535</a> |