

Inspection Photos

API: 043-06231

Operator: AUSCO PETROLEUM INC

Inspection Date: 10/15/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06231 | Date: 10/15/2021

Inspection Photos



Photo 1. Drone photo facing south toward the access road. There is erosion occurring down the road which is directed toward the stream at red arrow. The erosion along the road has not been repaired or stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/15/2021

Inspection Photos



Photo 2. Facing south along the access road. Erosion along the road has gotten worse since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/15/2021

Inspection Photos



Photo 3. Facing southwest along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/15/2021

Inspection Photos



Photo 4. The outlet of the stream crossing has eroded and washed out. There are wattles, liner and rock rip/rap that are now displaced into the stream bed. This area needs to be repaired immediately.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/15/2021

Inspection Photos



Photo 5. Facing southwest at the location. Unused areas of the location have not been reclaimed. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/15/2021

Inspection Photos



Photo 6. Facing toward the south side of the location. The soil piles are not maintained and there are undesirable weeds throughout this area. The soilpiles need to be replaced for interim reclamation. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/15/2021

Inspection Photos



Photo 7. Facing northwest toward the location. Interim reclamation has not been performed. There are undesirable weeds throughout the location. BMP's to control erosion are not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06231 | Date: 10/15/2021